United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SA40PC

This certificate, issued to DHL Air Cargo

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air

Regulations.

Original Product - Type Certificate Number A-765

Make: Beech

Model: E-18S-9700, Serial No. BA126, N8475D

Description of Type Design Change:

Modification of the cabin interior to an all cargo configuration in accordance with FAA approved DHL Top Drawing List dated July 28, 1981. Evaluation of cargo compartment based on following equipment installed: (1) Aerospace Products heavy flooring per STC SA1961WE, (2) Brownline floor tracks Part No 20276 per DHL Dwg 2, (3) Fleet Air straps Part No. 47827 MC-1, (4) Brownline nets/stude Part Nos. 21530-51 and 11251, (5) fire protection liners, (6) Aerospace Products cockpit escape hatch per STC SA3765WE and (7) hand held CO^2 fire extinguisher (5 1b).

Limitations and Conditions:

San 30,1961 DHL FAA approved Airplane Flight Manual (AFM) Supplement No. 1 dated July 28, 1981 is required and contains: (1) allowable compartment loads and floor load distributions, (2) cargo loading and tiedown procedures and (3) type and location of fire extinguisher. Data pertaining to this modification are considered inadequate for

duplication in other aircraft. This approval is limited to the installation made in Beech Model E-18S-9700, Serial No. BA126 only.

This certificate and the supporting data which is the basis for approval shall remain in effect until sur-

rendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the

Federal Aviation Administration.

Date of application July 28, 1981

Date reissued :

Date of issuance: August 12, 1981

Late amended .



By direction of the Administrator

(Signature)

Gary K. Nakagawa

Chief, Airworthiness District Office

Pacific-Asia RegionTitle)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.